
NEWSLETTER

NO. 114

350 BLEECKER STREET

NOVEMBER 18, 1998

It is urgent that immediately after the next hard rain everyone check their walls and ceilings to be sure no leaks appear. If there is any dampness at all (run your fingers over the likely spots) please fill in the form below and put it in the "Maintenance" box in the mail room immediately.

Our construction project, except for the lobby level walls, is almost finished. It is urgent that we know of any more leaks. Otherwise there may be substantial further damage.

Likely places to check include:

1. wall area around and below your air conditioners
2. wall area below your window sills
3. wall area above the windows
4. ceiling near windows
5. ceiling below terrace (if you live on the fifth floor)

The only alternative to "self inspection" would be entry by the engineer into every apartment. It would be expensive and intrusive to do this, so we'd like to avoid it.

If you have any questions about this or suggestions, please call any board member.

Thanks.

NAME: _____

Apt: _____

Day Phone: _____ Night Phone: _____

Where was the leak found? _____

Other comments: _____
